

Appendix B



Photograph #1: View looking south at 2925 and 2929 Ellis Road residential properties proposed to be demolished.



Photograph #2: Looking southeasterly, 2929 Ellis Road residential property in foreground, rising elevation is noted in the background.



Photograph #3: Looking south at 2931 Ellis Road residential property proposed to be demolished.



Photograph #4: Looking west from just north of the CRCSD bus office building at undeveloped land recently acquired by CRCSD.



Photograph #5: Looking southwest at the gasoline pump islands, located just northwest of the bus office building.



Photograph #6: Looking southwest at the above ground storage tanks (ASTs), located southwest of the CRCSD Bus Office Building.



Photograph #7: Looking south at the increase in elevation to the south of the current CRCSD bus office building.



Photograph #8: Looking east from the parking lot of the CRCSD bus office building at what appears to be a groundwater well.